

Metadata for Medical Imaging Diagnostics Use Case

Chest Xray – Data sample

```
"description": "",
  "tags": [
    {
      "id": 166832233, <image Id>
      "tagId": 32822771, <Annotation ID>
      "name": "Normal", <Classification>
      "value": "NO RADIOGRAPHIC ABNORMALITY DETECTED", <description>
      "labelerLogin": "vamsi.radiologist@digiquanta.com",
      "createdAt": "2025-03-24T08:51:40.804Z",
      "updatedAt": "2025-03-24T08:51:40.804Z"
    }
  ],
  "size": { <size of the bounding box>
    "height": 3520,
    "width": 4280
  },
  "objects": [
    {
      "id": 1673247681,
      "classId": 13768942,
      "objectId": null,
      "description": "",
      "geometryType": "rectangle",
      "labelerLogin": "vamsi.radiologist@digiquanta.com",
      "createdAt": "2025-03-21T07:30:53.515Z",
```

```
"updatedAt": "2025-03-21T07:30:53.515Z",
"tags": [],
"classTitle": "Normal",
"points": {
  "exterior": [
    [
      509,
      182
    ],
    [
      3506,
      3329
    ]
  ],
  "interior": []
}
],
"fileName": "File_000210_301"
},
```